A View from the Harbormaster

City of Annapolis

Presentation to the City Dock Advisory Committee

December 6, 2010


U.S. NAVAL ACADEMY
DOME
Band Stand
Santee Basin
TRITON
Fl (4+5) G 30s 25ft
Navy
MAST
Small Boat Basin
Piling
RESTRICTED ANCHORING
NO ANCHORING
LT OBSCURED
Fl (4+3) Y 30s 15ft Navy
Q 10ft
Navy
Stadium
CAPITOL DOME
POLIS
Market Slip
Priv buoys
SPIRE
Cable Area
Yacht Club
Sycamore Pt
SOUTH ANCHORAGE
110.159 (see note A)
MIDDLE GROUND
ANCHORAGE
110.159 (see note A)
Fl 6s 15ft 6M "HP"
Subm pile
Subm ruins
Horn Pt
NO ANCHORING
Pipeline Area
BASCULE BRIDGE
HOR CL 40 FT
VERT CL 15 FT
RESTRICTED ANCHORING
110.159 Annapolis Harbor, MD.
Except in the case of emergency, no vessel shall be anchored in this area without the permission of the Superintendent, U.S. Naval Academy. Anchorages will be assigned upon request to the Superintendent, U.S. Naval Academy.
EASTPORT
Fl G 4s 15ft 3M "5"
Fl R 2.5s 15ft 3M "2E"
Piling
1:12,000
ChartNavigator Pro - Copyright © 2005 Rose Point Navigation Systems, LLC. http://rosepointnav.com/

Colonial Times

City Dock Background

Transient Boat Activities

- 17 Rental Slips (Boats up to 65')
- 320' Concrete Bulkhead (East Side) (Boats up to 120')
- 120' Wooden Bulkhead (West Side)
- 76 Rental Moorings (Maximum Boat Size 45')
- 60 Annual Permit Moorings (maximum Boat Size 43')
- 2005 -- 12,000 Transactions
- 2009 -- 18,000 Transactions

Blue Angels Day

Blue Angels Day

Boat Show

Infrastructure Hazards

- 13,600 KVA Submarine Feeder Cable
- 16" Water main
- The Ground is low and spongy - Noteworthy High Tide five to six times a year
- Actions that restrict or limit Navigation Require Federal Approvals
- Some Actions will also Require State Approvals

DINGHY LANDING

STEVENS
STOP
DINGHY LANDING