Date: Aug 2012

TREE INVENTORY AND REPLACEMENT CALCULATIONS

Project: Milkshake Lane

Tree #	DBH (Diameter at 4.5 feet above grade)	Common Name	Botanical Name	Age Estimate	Condition Rating %	Condition Rating	Approx Canopy Radius (FT)	CRZ Critical Root Zone Radius in Ft (1.5 ft radius/in DBH)	Priority (1-4)	Tree Replacement: Within Roadway (Y/N)	Tree Replacement: Replacement Category	Tree Replacement: Replacements Required	Removal	Removal By Arborist	Additional Notes	Condition Notes
1	24	spruce, Norway	*Picea abies*	46	75	Good	17	36	1	NO	2	2	X		Some vine cover (bittersweet, poison ivy)	Small DW (1-2"), Vines,
2	52	beech, European	*Fagus sylvatica*	111	63	Fair	45	78	1	NO	3	0			Damaged, rotting trunk; copper cultivar, significant upper crown decline in 1 half, needs restoration prune, air layered limb, large trunk decay on declining side, english ivy at base, frass,	Large DW (3"+), Trunk Decay, Broken Limbs, Mechanical Damage,
3	44	pecan	*Carya illinoinensis*	105	67	Fair	40	66	2	NO	3	0			large broken leader (14")	Large DW (3"+), Broken Limbs, Vines,
4	38	pecan	*Carya illinoinensis*	90	53	Fair	28	57	2	NO	3	0			Trunk cavity at base, further inspection required	One Sided, Trunk Decay, Basal Decay,
5	14	spruce, Norway	*Picea abies*	28	70	Good	17	21	2	NO	1	0			Heavy vine cover (English ivy)	Small DW (1-2"), Vines,
6	7	boxelder	*Acer negundo*	12	63	Fair	15	11	3	NO	0.5	0			Vine cover (English ivy)	One Sided, Vines,
7	11	redcedar, eastern	*Juniperus virginiana*	31	66	Fair	15	17	2	NO	0.5	0			Vine cover (English ivy), broken limbs	Broken Limbs, Weak Union, Suppressed, Vines,
8	16	spruce, Norway	*Picea abies*	32	69	Fair	18	24	2	NO	1	0			Some vine cover (English ivy)	Vines,
9	21	spruce, Norway	*Picea abies*	42	70	Good	20	32	2	NO	2	2	X		Some vine cover (English ivy)	Vines,
10	23, 8	elm, spp.	*Ulmus spp.*	50	59	Fair	28	30	3	NO	3	3	X		Some crown dieback; 23, 8, crown decline\thin crown,	Large DW (3"+), Vines,
11	12	spruce, Norway	*Picea abies*	24	69	Fair	16	18	2	YES	1	0	X			One Sided, Vines,
12	16	spruce, Norway	*Picea abies*	32	72	Good	19	24	1	YES	1	0	X			Vines,
13	30	maple, red	*Acer rubrum*	78	63	Fair	27	45	3	NO	3	3	X		Some vine cover (English ivy)	Large DW (3"+), Broken Limbs, Weak Union, Vines,
14	22	oak, southern red	*Quercus falcata*	33	75	Good	29	33	1	YES	2	0	X			Full Crown,
15	7	dogwood, flowering	*Cornus florida*	20	59	Fair	14	11	3	NO	0.5	0			Some vine cover (English ivy); decline	Small DW (1-2"), Stressed, Vines,
16	7	dogwood, flowering	*Cornus florida*	20	55	Fair	14	11	3	NO	0.5	0				One Sided, Large DW (3"+), Stressed, Vines, Excessive Lean,
17	11	hornbeam, American	*Carpinus caroliniana*	28	63	Fair	20	17	1	NO	0.5	0			low branches	One Sided, Small DW (1-2"), Trunk Decay, Branch Decay, Weak Union, Vines,
18	29	pine, eastern white	*Pinus strobus*	63	58	Fair	21	44	3	NO	3	0			poor vigor, thin crown	Large DW (3"+), Broken Limbs, Stressed, Vines,
19	30	oak, willow	*Quercus phellos*	62	70	Good	34	45	1	NO	3	0				Full Crown, Large DW (3"+), Vines,
20	23	maple, red	*Acer rubrum*	58	41	Poor	25	35	4	NO	2	2		X	Broken leader	Broken Limbs, Weak Union, Serious Decline,
21	12	magnolia, southern	*Magnolia grandiflora*	19	69	Fair	16	18	1	NO	1	1		X	air layered,	One Sided, Excessive Lean,
22	14,14	holly, American	*Ilex opaca*	22	59	Fair	19	27	2	NO	3	3		X	Broken leader on one twin; damage from failed maple, thin crown,	Included Bark, Weak Union, Vines,
23	20	oak, southern red	*Quercus falcata*	30	67	Fair	30	30	1	NO	2	0			Heavy vine cover (English ivy)	One Sided, Large DW (3"+), Weak Union, Vines,
24	8	holly, American	*Ilex opaca*	13	66	Fair	10	12	2	NO	0.5	0				Included Bark, Weak Union, Vines,
25	29	oak, pin	*Quercus palustris*	57	70	Good	30	44	1	NO	3	3		X		Large DW (3"+), Weak Union, Vines,
26	9	holly, American	*Ilex opaca*	15	72	Good	13	14	2	NO	0.5	0.5	X			Vines,
27	10	holly, American	*Ilex opaca*	17	72	Good	14	15	2	NO	0.5	0.5		X		Full Crown, Vines,
28	27	oak, willow	*Quercus phellos*	57	70	Good	30	41	1	NO	3	0			Some vine cover (English ivy)	One Sided, Vines,
29	31	oak, willow	*Quercus phellos*	66	70	Good	30	47	1	NO	3	0			Vine cover (English ivy) & broken limbs	One Sided, Large DW (3"+), Vines,
30	9,5,4	maple, red	*Acer rubrum*	28	63	Fair	13	18	3	NO	2	0				One Sided, Small DW (1-2"), Weak Union,
31	9	maple, red	*Acer rubrum*	22	59	Fair	15	14	3	NO	0.5	0			Cavity	One Sided, Trunk Decay, Basal Decay,
32	7	hornbeam, American	*Carpinus caroliniana*	18	61	Fair	12	11	2	NO	0.5	0				One Sided, Excessive Lean,
33	15	hornbeam, American	*Carpinus caroliniana*	38	50	Fair	20	23	3	NO	1	1	X			Included Bark, Weak Union, Stressed,
34	12	hornbeam, American	*Carpinus caroliniana*	30	56	Fair	12	18	3	NO	1	1		X		One Sided, Trunk Decay, Stressed, Vines,
35	7	dogwood, flowering	*Cornus florida*	20	59	Fair	12	11	3	NO	0.5	0.5	X			One Sided, Small DW (1-2"), Trunk Decay, Vines,
36	9,8	dogwood, flowering	*Cornus florida*	23	50	Fair	13	17	3	NO	1	0			dead leader	Included Bark, Weak Union, Stressed, Serious Decline, Excessive Lean,
37	10	holly, American	*Ilex opaca*	17	70	Good	15	15	2	NO	0.5	0				Vines,
38	12,6,3	holly, Chinese	*Ilex cornuta*	13	70	Good	12	21	2	NO	2	2	X		3-trunk; leaves entire, Burford	Vines,
39	18	oak, southern red	*Quercus falcata*	26	72	Good	18	27	1	NO	2	2	X		vine cover (English ivy), possibly topped	Vines,
40	8	dogwood, flowering	*Cornus florida*	23	73	Good	15	12	2	YES	0.5	0	X			Small DW (1-2"), Vines,
41	6	dogwood, flowering	*Cornus florida*	17	69	Fair	10	9	3	YES	0.5	0	X			One Sided, Vines,
42	6,10	magnolia, southern	*Magnolia grandiflora*	13	64	Fair	12	17	2	NO	1	1	X		vine cover (English ivy); twin	Weak Union, Stressed, Vines,
43	38	pecan	*Carya illinoinensis*	88	66	Fair	40	57	2	NO	3	0				One Sided, Weak Union, Vines,
44	20	pecan	*Carya illinoinensis*	50	70	Good	22	30	2	NO	2	0				One Sided, Suppressed,
45	40	pecan	*Carya illinoinensis*	95	72	Good	38	60	1	NO	3	0				Full Crown, Vines,
46	31	pecan	*Carya illinoinensis*	78	63	Fair	25	47	2	NO	3	0			Lightning strike; broken limbs	One Sided, Broken Limbs, Vines, Mechanical Damage,
47	15	pecan	*Carya illinoinensis*	38	75	Good	20	23	1	NO	1	1	X			Vines,
48	9	goldenraintree	*Koelreuteria paniculata*	18	75	Good	15	14	1	NO	0.5	0.5	X			
49	10	pear, Callery	*Pyrus calleryana*	15	72	Good	10	15	3	NO	0.5	0.5	X			Weak Union,
50	30	locust, black	*Robinia pseudoacacia*	66	44	Poor	20	45	4	NO	3	3	X		Severe crown dieback, broken limbs	Weak Union, Serious Decline,
51	15,13	apple, common	*Malus pumila*	23	59	Fair	13	27	2	YES	3	0	X		twin	Trunk Decay, Broken Limbs,
52	7	pear, Callery	*Pyrus calleryana*	11	69	Fair	12	11	3	YES	0.5	0	X			Weak Union,
53	7	locust, black	*Robinia pseudoacacia*	18	70	Good	12	11	2	NO	0.5	0			Broken limbs	Small DW (1-2"),
54	11	maple, red	*Acer rubrum*	31	47	Poor	12	17	4	NO	0.5	0.5	X		Broken leader	Weak Union,
55	8,8	apple, common	*Malus pumila*	13	50	Fair	15	17	3	NO	1	1	X		Broken limbs, weak crotch	Large DW (3"+), Trunk Decay, Branch Decay, Broken Limbs, Weak Union, Vines,
56	46	boxelder	*Acer negundo*	79	44	Poor	35	69	3	NO	3	3	X		Trunk cavity/ large decay area, crown dieback, vine cover	Trunk Decay, Branch Decay, Stressed, Vines,
57	15	pecan	*Carya illinoinensis*	38	72	Good	25	23	2	NO	1	1	X			Vines,
58	10	magnolia, southern	*Magnolia grandiflora*	16	72	Good	14	15	2	NO	0.5	0.5	X			
59	25	elm, American	*Ulmus americana*	54	70	Good	33	38	1	NO	3	0				Full Crown, Vines,
60	21	elm, American	*Ulmus americana*	46	70	Good	27	32	1	YES	2	0	X			Large DW (3"+), Branch Decay, Vines,
61	13	honeylocust	*Gleditsia triacanthos*	25	66	Fair	18	20	3	NO	1	1	X		Some vine cover (English ivy)	Small DW (1-2"), Vines,
62	10,8,6	tree of heaven	*Ailanthus altissima*	22	59	Fair	18	24	4	NO	2	2	X		Crown dieback	Trunk Decay, Weak Union, Vines,
63	38	pecan	*Carya illinoinensis*	85	70	Good	34	57	1	NO	3	0				Trunk Decay, Broken Limbs, Vines,
64	20	catalpa, northern	*Catalpa speciosa*	63	61	Fair	16	30	2	NO	2	2	X		vine cover (poison ivy); crown dieback	Branch Decay, Vines,
65	21	chestnut, Chinese	*Castanea mollissima*	42	66	Fair	30	32	2	NO	2	2	X			One Sided, Large DW (3"+),
66	24	oak, southern red	*Quercus falcata*	38	63	Fair	20	36	2	NO	2	0			Broken limbs	One Sided, Small DW (1-2"), Broken Limbs, Stressed, Vines,
67	14	locust, black	*Robinia pseudoacacia*	37	59	Fair	20	21	3	NO	1	1	X		Broken limbs, vine cover (grape)	Stressed, Vines,
68	8	osage-orange	*Maclura pomifera*	18	61	Fair	14	12	3	NO	0.5	0.5	X		Leaning, vine cover (English ivy)	Broken Limbs,
69	17	cherry, black	*Prunus serotina*	43	63	Fair	15	26	3	NO	1	0			Broken limbs	Large DW (3"+), Broken Limbs, Weak Union, Vines,
70	14	oak, willow	*Quercus phellos*	26	56	Fair	15	21	3	NO	1	0			Broken limbs\leader	One Sided, Large DW (3"+), Broken Limbs, Vines,
71	8	oak, willow	*Quercus phellos*	17	56	Fair	12	12	3	NO	0.5	0				One Sided, Large DW (3"+), Broken Limbs, Vines,
72	8	oak, willow	*Quercus phellos*	17	70	Good	12	12	2	NO	0.5	0				Vines,

DAVEY RESOURCE GROUP
A Division of The Davey Tree Expert Company

Date: Aug 2012

TREE INVENTORY AND REPLACEMENT CALCULATIONS

Project: Milkshake Lane

Tree #	DBH (Diameter at 4.5 feet above grade)	Common Name	Botanical Name	Age Estimate	Condition Rating %	Condition Rating	Approx Canopy Radius (FT)	CRZ Critical Root Zone Radius in Ft (1.5 ft radius/in DBH)	Priority (1-4)	Tree Replacement: Within Roadway (Y/N)	Tree Replacement: Replacement Category	Tree Replacement: Replacements Required	Removal	Removal By Arborist	Additional Notes	Condition Notes
73	11	cherry, black	*Prunus serotina*	28	53	Fair	12	17	3	NO	0.5	0			Crown dieback, heavy vine cover	One Sided, Stressed, Vines, Excessive Lean,
74	19	cherry, black	*Prunus serotina*	48	53	Fair	14	29	3	NO	2	0			Crown dieback, heavy vine cover;; poor form	Large DW (3"+), Vines,
75	17	cherry, black	*Prunus serotina*	43	56	Fair	15	26	3	NO	1	1	X		Broken limbs; decline	Large DW (3"+), Vines,
76	14	elm, American	*Ulmus americana*	30	66	Fair	24	21	2	NO	1	1		X	Some vine cover (poison ivy)	Broken Limbs, Vines,
77	15	cherry, black	*Prunus serotina*	38	72	Good	25	23	2	YES	1	0	X			Large DW (3"+), Vines,
78	9	cherry, black	*Prunus serotina*	23	53	Fair	10	14	3	YES	0.5	0	X			Vines, Excessive Lean,
79	23	cherry, black	*Prunus serotina*	50	69	Fair	25	35	2	NO	2	2		X		Vines, Overhead Utility,
80	8	tree of heaven	*Ailanthus altissima*	18	69	Fair	12	12	3	NO	0.5	0				Overhead Utility,
81	7	redcedar, eastern	*Juniperus virginiana*	20	72	Good	9	11	2	NO	0.5	0.5	X			Small DW (1-2"), Vines,
82	15	cherry, black	*Prunus serotina*	38	63	Fair	16	23	3	NO	1	1	X		Vine cover (English ivy)	Vines,
83	9	cherry, black	*Prunus serotina*	23	66	Fair	14	14	2	NO	0.5	0.5	X		Vine cover (English ivy), crown dieback	Broken Limbs, Vines,
84	12	cherry, black	*Prunus serotina*	30	34	Poor	8	18	4	NO	1	1	X		Leaning, broken limbs; topped from utility	Overhead Utility, Excessive Lean,
85	15	elm, American	*Ulmus americana*	33	64	Fair	22	23	2	NO	1	1	X		Heavy vine cover (English ivy)	Large DW (3"+), Vines,
86	10	cherry, black	*Prunus serotina*	25	55	Fair	10	15	3	NO	0.5	0.5	X		Vine cover (English ivy), crown dieback	Vines,
87	16,12	cherry, black	*Prunus serotina*	40	58	Fair	17	27	3	NO	3	3	X		Leaning, vine cover (English ivy)	Vines,
88	7	elm, slippery	*Ulmus rubra*	15	55	Fair	12	11	3	NO	0.5	0.5	X		Vine cover (English ivy), broken limbs	Vines, Excessive Lean,
89	8	cherry, black	*Prunus serotina*	18	64	Fair	13	12	2	NO	0.5	0.5	X		Vine cover (English ivy)	One Sided, Suppressed, Vines,
90	19	cherry, black	*Prunus serotina*	33	50	Fair	18	29	3	NO	2	2	X		3-trunk, vine cover; broken limbs	Large DW (3"+), Broken Limbs, Vines,
91	11	pear, common	*Pyrus communis*	17	63	Fair	15	17	2	NO	0.5	0.5	X		tall specimen,	Broken Limbs, Vines,
92	38	cherry, black	*Prunus serotina*	95	47	Poor	40	57	3	NO	3	3	X		Twin with weak crotch, crown dieback, heavy vine cover, broken limbs	Large DW (3"+), Vines,
93	11	cherry, black	*Prunus serotina*	28	55	Fair	8	17	3	NO	0.5	0.5	X		Leaning, vine cover (English ivy)	Large DW (3"+), Broken Limbs, Vines, Excessive Lean,
94	28	cherry, black	*Prunus serotina*	70	56	Fair	25	42	3	NO	3	3	X		Leaning, vine cover (English ivy)	Vines, Overhead Utility,
95	18	pine, eastern white	*Pinus strobus*	45	66	Fair	15	27	2	NO	2	2	X		Broken limbs	One Sided, Broken Limbs, Vines, Overhead Utility,
96	20	pine, eastern white	*Pinus strobus*	50	72	Good	16	30	2	NO	2	2	X		Broken limbs	Vines,
97	15	pine, eastern white	*Pinus strobus*	38	59	Fair	14	23	3	NO	1	1	X		Broken limbs	One Sided, Broken Limbs, Vines, Overhead Utility,
98	11	elm, spp.	*Ulmus spp.*	24	63	Fair	12	17	3	NO	0.5	0.5	X			Vines, Overhead Utility,
99	17	chestnut, Chinese	*Castanea mollissima*	34	59	Fair	22	26	3	NO	1	1	X		Severe crown dieback	One Sided, Large DW (3"+), Vines,
100	7	apple, common	*Malus pumila*	12	53	Fair	10	11	3	NO	0.5	0.5	X		Broken limbs	Large DW (3"+), Trunk Decay,
101	21	cherry, black	*Prunus serotina*	53	66	Fair	25	32	2	NO	2	0			Broken limbs, vine cover	Broken Limbs, Vines, Overhead Utility,
102	9	pine, eastern white	*Pinus strobus*	23	38	Poor	12	14	4	NO	0.5	0.5		X	Crown dieback, heavy vine cover	Serious Decline,
103	15	catalpa, northern	*Catalpa speciosa*	50	53	Fair	20	23	3	NO	1	1	X		Crown dieback	Large DW (3"+), Vines, Serious Decline,
104	17	catalpa, northern	*Catalpa speciosa*	57	61	Fair	18	26	2	NO	1	1	X		Crown dieback	Small DW (1-2"), Weak Union, Vines,
105	23	catalpa, northern	*Catalpa speciosa*	77	72	Good	18	35	2	NO	2	2	X		Vine cover (English ivy)	Small DW (1-2"), Vines,
106	10	cherry, black	*Prunus serotina*	25	66	Fair	11	15	3	NO	0.5	0.5	X		Vine cover (English ivy)	Vines,
107	21	catalpa, northern	*Catalpa speciosa*	70	70	Good	20	32	2	NO	2	2	X			Small DW (1-2"), Vines,
108	18	catalpa, northern	*Catalpa speciosa*	60	67	Fair	15	27	2	NO	2	2		X		One Sided, Small DW (1-2"), Vines,
109	15	cherry, black	*Prunus serotina*	38	56	Fair	18	23	3	NO	1	1	X		Heavy vine cover (English ivy)	Vines, Excessive Lean,
110	13	elm, spp.	*Ulmus spp.*	28	56	Fair	14	20	3	NO	1	1	X		Leaning, vine cover (English ivy)	Vines, Excessive Lean,
111	13	elm, spp.	*Ulmus spp.*	28	72	Good	16	20	2	NO	1	1	X			Vines,
112	28	cherry, black	*Prunus serotina*	70	48	Poor	20	42	4	NO	3	3	X		Leaning, crown dieback, broken limbs	Large DW (3"+), Root Damage/Decay, Vines, Overhead Utility, Excessive Lean,
113	16	cherry, black	*Prunus serotina*	40	64	Fair	12	24	3	NO	1	1	X		Heavy vine cover (English ivy); topped by utility	Overhead Utility, Excessive Lean,
114	8	pine, eastern white	*Pinus strobus*	20	50	Fair	10	12	3	NO	0.5	0.5	X		poor form	Vines,
115	22	cherry, black	*Prunus serotina*	55	63	Fair	18	33	3	NO	2	2	X		Vine cover (English ivy)	Vines, Overhead Utility,
116	12	cherry, black	*Prunus serotina*	30	58	Fair	15	18	3	NO	1	1	X		Leaning, broken limbs	Trunk Decay, Vines, Overhead Utility,
117	10	pear, Callery	*Pyrus calleryana*	15	59	Fair	10	15	3	NO	0.5	0.5	X			Trunk Decay, Vines, Overhead Utility,
118	24	maple, red	*Acer rubrum*	67	56	Fair	18	36	3	NO	2	2	X		Vine cover (English ivy)	Large DW (3"+), Trunk Decay, Vines, Overhead Utility,
119	20	cherry, black	*Prunus serotina*	50	38	Poor	18	30	4	NO	2	2	X		Severe crown dieback	Overhead Utility, Serious Decline,
120	18	pine, eastern white	*Pinus strobus*	45	63	Fair	12	27	3	NO	2	2	X		Leaning, vine cover (English ivy)	Small DW (1-2"), Vines, Overhead Utility,
121	12	locust, black	*Robinia pseudoacacia*	32	69	Fair	16	18	2	NO	1	1	X			Overhead Utility,
122	11	pine, eastern white	*Pinus strobus*	28	56	Fair	12	17	3	NO	0.5	0.5	X		Broken limbs	One Sided, Broken Limbs, Vines, Overhead Utility,
123	13	cherry, black	*Prunus serotina*	30	48	Poor	12	20	3	NO	1	1	X		Leaning, broken leader	Trunk Decay, Broken Limbs, Excessive Lean,
124	16	oak, sawtooth	*Quercus acutissima*	23	63	Fair	18	24	2	NO	1	1	X		Crown dieback, vine cover (English ivy)	Broken Limbs, Stressed, Vines, Overhead Utility,
125	12	elm, American	*Ulmus americana*	20	63	Fair	15	18	3	NO	1	1	X		severe vines	Vines,
126	13	locust, black	*Robinia pseudoacacia*	34	44	Poor	14	20	4	NO	1	1	X			Large DW (3"+), Trunk Decay, Vines, Excessive Lean,
127	11,8	pear, common	*Pyrus communis*	17	58	Fair	12	20	3	NO	2	2	X		Broken limbs	Trunk Decay, Broken Limbs, Weak Union,
128	9,10,3	cherry, black	*Prunus serotina*	23	70	Good	13	23	2	NO	2	0			3-trunk	Weak Union,
129	7	mulberry, spp.	*Morus spp.*	11	72	Good	15	11	2	NO	0.5	0				Weak Union,
130	12	pine, eastern white	*Pinus strobus*	30	75	Good	12	18	2	NO	1	0				
131	12	pine, eastern white	*Pinus strobus*	30	75	Good	12	18	2	NO	1	0				
132	11	pine, eastern white	*Pinus strobus*	28	73	Good	13	17	2	NO	0.5	0				
133	10	ash, white	*Fraxinus americana*	16	69	Fair	13	15	2	NO	0.5	0.5	X		Some crown dieback	Small DW (1-2"), Stressed,
134	10	ash, white	*Fraxinus americana*	18	50	Fair	12	15	3	NO	0.5	0.5	X		Crown dieback, broken limbs	Serious Decline,
135	13	catalpa, northern	*Catalpa speciosa*	43	56	Fair	15	20	3	NO	1	1	X		Severe crown dieback	One Sided, Stressed, Serious Decline,
136	10	pine, eastern white	*Pinus strobus*	25	66	Fair	10	15	3	NO	0.5	0.5	X			Included Bark, Weak Union,
137	8	pine, eastern white	*Pinus strobus*	20	59	Fair	10	12	3	NO	0.5	0.5	X		Crown dieback	Small DW (1-2"), Stressed,
138	9	ash, white	*Fraxinus americana*	16	64	Fair	13	14	2	NO	0.5	0.5	X			Vines,
139	9	ash, white	*Fraxinus americana*	16	63	Fair	12	14	2	NO	0.5	0.5	X			
140	10	ash, white	*Fraxinus americana*	18	63	Fair	12	15	3	NO	0.5	0.5	X			
141	11	ash, white	*Fraxinus americana*	19	55	Fair	15	17	3	NO	0.5	0.5	X		Crown dieback	Weak Union, Stressed, Vines,
142	14	cherry, black	*Prunus serotina*	35	38	Poor	0	21	4	NO	1	0			severe lean over adjacent yard and utility	Overhead Utility, Serious Decline, Excessive Lean,
									TOTALS:	10		114	89	10		

TREE REPLACEMENT NOTE:

- 114 REPLACEMENT TREES REQUIRED FOR TREES PROPOSED TO BE REMOVED BY CONSTRUCTION
- 49 ADDITIONAL REPLACEMENT TREES REQUIRED FOR MITIGATION OF TREES PREVIOUSLY REMOVED
- 163 TOTAL REPLACEMENT TREES REQUIRED

DAVEY RESOURCE GROUP
A Division of The Davey Tree Expert Company

DRAWN: C.J.H.
DESIGN: C.J.H.
CHECKED: C.A.C.
REV. NO. 0

BASED ON PLANS PROVIDED BY BAY ENGINEERING

REV. | DATE | COMMENT | BY

STATE OF MARYLAND LICENSED FORESTER NO. 666 DAVID A. ZEITLIN BOARD OF FORESTERS

DAVEY RESOURCE GROUP
A Division of The Davey Tree Expert Company

Land Development Solutions
2138 Priest Bridge Ct, Suite 4, Crofton, MD 21114
Office 410.774.0024 • Fax 310.858.0184
National 877.818.7337

PRELIMINARY FOREST CONSERVATION PLAN

PRIMROSE HILL
3 MILKSHAKE LANE
CITY OF ANNAPOLIS, MARYLAND

CLIENT: ELM STREET DEVELOPMENT

SCALE 1" = 30'

DATE: 07/02/2013

SHEET NO: LJ-104

THIS PLAN IS FOR TREE PRESERVATION PURPOSES ONLY AND NOT FOR CONSTRUCTION. THE PROFESSIONAL'S SEAL IS INVALID ON ANY PLOT THAT DOES NOT INCLUDE AN ORIGINAL INK SIGNATURE.

Y:\2012\Milkshake Lane\dwg\DRG\DRG_Milkshake_TP_2013.07.02_fcp.dwg, 7/3/2013 11:27:20 AM, HulseC, HP Designjet Z5200ps PCL3.pc3, ARCH D (landscape), Davey Resource Group, Land Development Solutions